

### Labor and Materials

1	Copper	Lead	Connection	$\frac{3}{4}$ "		\$
1	Curb	<div style="display: flex; align-items: center;"> <div style="font-size: 2em; margin-right: 5px;">}</div> <div style="margin-right: 5px;">Eock Valve T. S. &amp; V.</div> </div>		1 in		\$
1	Service Box	Old-returnd-	<div style="display: flex; align-items: center;"> <div style="font-size: 2em; margin-right: 5px;">}</div> <div style="margin-right: 5px;">Short 3 1/2 x 4 1/2 Long 4 1/2 x 5 1/2 Buff. or Rdway</div> </div>			\$
18	Ft.	1 in.	<div style="display: flex; align-items: center;"> <div style="font-size: 2em; margin-right: 5px;">}</div> <div style="margin-right: 5px;">Copper Galv Iron Cast Iron</div> </div>	Pipe at		\$
	Nipples		in. at			\$
	Bushings		to	in. at		\$
	Red'g Inc'g	Conplings		to	in. at	\$
	Union		in. at			\$
	Meter		in. at			\$
	Lead Joints		at			\$
	Leadite Joints		at			\$
	Hrs. Foreman		at			\$
	Hrs. Chauffeur		at			\$
	Hrs. Tapper		at			\$
	Hrs. Labor		at			\$
	Hrs. Labor		at			\$
	Hrs. Compressor		at			\$
	Compensation Ins.					\$
	Trucking					\$
	Builders Use of Water					\$
						\$
						\$
						\$
						\$
						\$
						\$
						\$

St. 350  
 Pl. 203  
 Ave. No.

---

Name of Owner  
*EP P...*

---

Labor and Mat'l. Report 4/17/19 19

---

350

6" Main *Sherman Ave* Elev. of Main at tap.....  
 Gate at ● Gate at ●  
 ● Curb Box  
*Church Property*

