

LABOR AND MATERIALS

1 Copper } Connection _____ \$ _____
~~Lead~~
 1 Curb } Cock } _____ in. _____ \$ _____
 } Valve }
 } T.S. & V. }
 1 Service box { Short 3-1/2 x 4-1/2 } _____ \$ _____
 Old returned { Long 4-1/2 x 5-1/2 }
 20 Ft. _____ in. { Copper } Pipe at _____ \$ _____
 } Est. }
 _____ Nipples _____ in. at _____ \$ _____
 _____ Bushings _____ to _____ in. at _____ \$ _____
 _____ Red'g _____
 _____ Inc'g _____
 _____ Union _____ in. at _____ \$ _____
 _____ Meter _____ in. at _____ \$ _____
 _____ \$ _____
 _____ Compound Joints at _____ \$ _____
 _____ Maintenance Foreman _____ \$ _____
 _____ Hrs. Water Maint. Man - 1 at _____ \$ _____
 _____ Hrs. Water Maint. Man - 2 at _____ \$ _____
 _____ Hrs. Garage Foreman _____ at _____ \$ _____
 _____ Hrs. Labor _____ at _____ \$ _____
 _____ Hrs. Compressor at _____ \$ _____
 _____ \$ _____
 _____ Trucking _____ \$ _____
 _____ Pav't Patch _____ \$ _____
 _____ \$ _____
 _____ \$ _____
 _____ \$ _____
 _____ \$ _____
 _____ \$ _____

GOODWIN Ave. No. 37
 Name of Owner

LOT TAP

Labor and Mat'l. Report 19 30, JUNE 11

TREE
 24 33-4

● Curb Box

4" Main Elev. of Main at tap 5'

Gate at ● Gate at

● Curb Box

CANNOT LOCATE - LEON-
 8-12-65