	TA .
	*
LABOR AND MATERIALS	
2771	
/ Copper Connection	
Locate	
Curb Cock	
T. S. & V.	Φ
Service box Short 3½ x 4½	1 1 4
Old returned Suff or Rdway	10
	2
ZZ Ft. 1/4in. Copper Pipe at	9
-G.I.	
Nipples in at	S
Bushings to in. at	
Red'g	φ
Inc'g Coupl'gs to in. at	S
Union in, at	
2004 THE COLUMN TO A STATE OF THE PARTY OF T	-DMC SHEEZH DOODSON AND STORES
Meter in, at	14
Lead Joints at	
Compound Joints at	\$
Maintenance Foreman	\$
Hrs. Water Maint. Man-1 at	\$
Hrs. Water Maint. Man-2 at	
Hrs. Garage Foreman at	
_	
Hrs. Labor—at	
Hrs. Compressor at	
Compensation Ins. at \$per C	\$
Trucking	\$
Pav't Patch	\$
Tap by GIF Gord + Co.	\$
3-27-6/	
	\$
O'head	\$
The state of the s	\$
	100
	40 6
A	

R-inside - near door
Glen St. 100 Ph. Ave. No. 106
Name of Owner The Post Go.
Labor and Mat'l. Report Mar. 27 196/  Rear of Bldg South  Cold Park Theatre)
Copper Pipe Curb Box 43'2"  Elev. of
Main at tap 5 Gate at  TAX ID #310.5-1-15
• Curb Box
NEW CURB STOP-1998
LSM-5C-2.5 5e