

### LABOR AND MATERIALS

Copper	} Connection	-----	\$
Lead		-----	\$
Curb	} Cock Valve T. S. & V.	----- in.	\$
Service Box		-----	\$
Old returned	} Short 3 1/2 x 4 1/2 Long 4 1/2 x 5 1/2 Buff. or Rdway	-----	\$
Ft. ----- in.		-----	\$
		-----	\$
	} Copper Galv Iron Cast Iron	Pipe at	\$
Nipples		----- in. at	\$
Bushings		----- to ----- in. at	\$
Red'g Inc'g	} Couplings	----- to ----- in. at	\$
Union		----- in. at	\$
Meter	----- in. at	\$	
Lead Joints	at	\$	
Leadite Joints	at	\$	
Hrs. Foreman	at	\$	
Hrs. Chauffeur	at	\$	
Hrs. Tapper	at	\$	
Hrs. Labor	at	\$	
Hrs. Labor	at	\$	
Hrs. Compressor	at	\$	
Compensation Ins.		\$	
Trucking		\$	
Builders Use of Water		\$	
		\$	
		\$	
		\$	
		\$	
		\$	

St. 347-357  
 Pt. Glen  
 Ave. No. 223

Name of Owner \_\_\_\_\_

---

Labor and Mat'l. Report Dec. 4 1939

Hydrant 347-357  
Was  
Near

Main

Curb Box

Manhole

Gate at

Gate at

Curb Box

old hydrant tap

Disconnected from Main at 4-65

Measurements are from center of manholes.