

### Labor and Materials

Copper	Connection	3/4"		96
Lead				
Curb	Cock Valve T.S.&V.	2 1/4" in		133
Service Box	Old returned	Short 3 1/2 x 4 1/2 Long 4 1/2 x 5 1/2 Buff. or Rdway		135
25 Ft. 3/4" in.	Copper Galv. Iron Cast-Iron	Pipe at		3.75
Nipples	in. at			
Bushings	to in. at			
Red'g Inc'g	Couplings	to in. at		
Union	in. at			
Meter	in. at			
Lbs. Br. Stone	at			
Lbs. Sand	at			
Bags Cement	at			
Paving Brick	at	Mack		
		Red		
		Asphalt		
Lead Joints	at			
Leadite Joints	at			
Hrs. Foreman	at			
Hrs. Common Labor	at			
Hrs. Common Labor	at			
Hrs. Mason	at			
Hrs. Masons Helper	at			
Hrs. Compressor	at			
Compensation Ins				
Trucking				
Builders Use of Water	Patch			35.-
Total \$				

102 ✓ 36 42


Labor and Material Report *NOV 6* 1936

---

42

*36 Grand St 3/4 TAP*

*Eddy*



● Curb Box

---

496 Main Elev. of Main at tap *14*

---

Gate at ● TAX ID # 302.16-17-51 ● Gate at

---

● Curb Box

*old shut off*

*TH*