LABOR AND MATERIALS

Copper } Connection 4	\$
Curb Curb \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \	\$
Service box Short 3-1/2 x 4-1/2 Old returned Short 3-1/2 x 4-1/2	\$
$\frac{28}{2}$ Ft. $\frac{34}{4}$ in. $\frac{\text{Copper}}{4}$ Pipe at	\$
Nipples in. at	\$
Bushings to in. at	\$
Red'g	
Inc'g	
Union in. at	\$
Meter in. at	
	\$
Compound Joints at	
Maintenance Foreman	_ \$
Hrs. Water Maint. Man - 1 at	\$
Hrs. Water Maint. Man - 2 at	\$
Hrs. Garage Foreman at	\$
Hrs. Labor at	\$
Hrs. Compressor at	_ \$
	_ \$
Trucking	_ \$
Pav't Patch	_ \$
	\$
	_ \$
	s
	_ \$
	\$

GRAND	St -91. -Av		10
Name of Owner			
======			
Labor and Mat'l. Repor	t 1928, DE	C./0	
	Z 26'9"	30'	
		ıb Davi	
	Cur	ъ Вох	
	Elev Mai	/. of n at tap_	4± '
Gate at 🌘			Gate at
	Curb	Box	
OLD LEAD	DISCON	WECT	F.D