LABOR AND MATERIALS	
Copper { Connection 3/4" \$.  Lead Cock Valve } 3/4 in. \$.	229
1-3.0cV.	270
Service box Old returned Short 3½x4½ Long 4½x5½ Buff or Rdway \$	4.25
	780
Nipples in. at \$ Bushings to in. at \$	
Inc'g Coupi gstoin. at	
Unionin. at\$	
Meterin. at\$	
Lead Joints at\$	
Compound Joints at\$	
Hrs. Water Maint. Man-1 at	
2Hrs. Water Maint. Man-2 at 1.02 \$	204
Hrs. Labor—at\$	105
2Hrs. Labor—at 91 \$	1.82
Hrs. Compressor at S	
Compensation Ins. at \$per C\$	09
Trucking\$	100
Pav't Patch	
	***************************************
	A THE PARTY OF THE
O'head	11
	16.49

77-1556	Enforc Faving
y <sup>8</sup> a 30 €	St.
Gran	Pt: Ave: No. 13
Name of Owner	
- Mary	Daker.
Labor and Mat'l. Report	July 5 1950
	#13
7.4'5"	34'9"
677	Curb Box
Main	Elev. of Main at tap
Gate at •	• Gate at
	- Oate at
	• Curb Box
2 2	
SM-5C 10-21-49	