LABOR AND MATERIALS

Copper Connection 3/4	_ \$
Cock Vertice Fig. 8 V: 3/4 in.	\$
Service box Short 3-1/2 × 4-1/2 Old returned Leng 4-1/2 × 5-1/2	\$
	\$
Nipples in. at	s
Bushings to in. at	
Red'g	
Inc'g	•
Union in. at	\$
Meter in. at	
560	
Compound Joints at	
Maintenance Foreman	
Hrs. Water Maint. Man - 1 at	
Hrs. Water Maint. Man - 2 at	\$
Hrs. Garage Foreman at	
Hrs. Labor at	
Hrs. Compressor at	
Trucking	6210
Pav't Patch	
144 (1915)	40
	500
	\$
	\$

€	Curb Box
Gate at •	• Gate a
Main	Elev. of Main at tap
	Curb Box
60	5. 2
8	
Labor and Mat'l. Report 19 ¹	-17, May 7
Name of Owner KIRPATI	RICK
GRANT	St: Pt: Ave. No