## LABOR AND MATERIALS

Copper } Connection 3/4	\$
Curb Cock 3/4 in.	\$
∫ F.Sa-V. ∫ Service box ∫ Short 3-1/2 x 4-1/2 }	¢
Service box Short 3-1/2 x 4-1/2 Old-returned Long 4-1/2 x 5-1/2	
Ft. 3/4 in. Copper Pipe at	\$
Nipples in. at	\$
Bushings to in. at	\$
Red'g	
Inc'g	
Union in. at	\$
Meter in. at	\$
	\$
Compound Joints at	\$
Maintenance Foreman	\$
Hrs. Water Maint. Man - 1 at	\$
Hrs. Water Maint. Man - 2 at	\$
Hrs. Garage Foreman at	\$
Hrs. Labor at	
Hrs. Compressor at	
	\$
Trucking	
Pav't Patch	
	4
	-
,	- ·
	-

- 1 × 1	<del>St</del> :
GRANT	Pt. Ave. No. 55
Name of Owner	
Labor and Mat'l. Report 192.	5, NOV. 24
(2)	39/1/11
	Curb Box
11	/
Main	Elev. of HZ
Gate at	<ul><li>Gate at</li></ul>
·	y
	Curb Box

## LABOR AND MATERIALS

Copper Connection	\$
Curb Cock Valve T.S. & V.	\$
Service box {Short 3-1/2 x 4-1/2 } Old returned {Long 4-1/2 x 5-1/2 }	_ \$
Ft in. { Copper G.I. C.I. } Pipe at	_ \$
Nipples in. at	\$
Bushings to in. at	\$
Red'g	
Inc'g	
Union in. at	\$
Meter in. at	
	\$
Compound Joints at	_ \$
Maintenance Foreman	
Hrs. Water Maint. Man - 1 at	
Hrs. Water Maint. Man - 2 at	_ \$
Hrs. Garage Foreman at	_ \$
Hrs. Labor at	
Hrs. Compressor at	
Trucking	
Pav't Patch	
<del></del>	\$

-GRANT	St. Pl. Ave. No
Name of Owner	
Labor and Mat'l. Report	6.3-2014
L	L9'
	CLEANOVS
Main	Elev. of Main at tap
Gate at ●	• Gate at
-	Curb Box