LABOR AND MATERIALS

Copper } Connection 3/4"	_ \$
Cock > 31.	
Curb Velve	Ψ
Service box Short 3-1/2 x 4-1/2 Old returned Leng 4-1/2 x 5-1/2	_,\$
$\frac{28}{2}$ Ft. $\frac{34}{4}$ in. $\frac{20}{6}$ Pipe at	_ \$
Nipples in. at	_ \$
Bushings to in. at	_ \$
Red'g	
Inc'g	
Union in. at	_, \$
Meter in. at	_ \$
	_ \$
Compound Joints at	_ \$
Maintenance Foreman	_ \$
Hrs. Water Maint. Man - 1 at	_ \$
Hrs. Water Maint. Man - 2 at	_ \$
Hrs. Garage Foreman at	\$
Hrs. Labor at	_ \$
Hrs. Compressor at	\$
<u> </u>	\$
Trucking	_ \$
Pav't Patch	\$
	\$
	\$
	\$

GRANT	Ave. No. 113
Name of Owner	Ave. No
* VACANT LOT	- M
- VALPIVI LOS	EK .
Labor and Mat'l. Report 19,3	5, NOV. 8
#115	#111
57911	56 3
	Curb Box
Main	Elev. of Main at tap 4 1/Z
Gate at ●	Gate at
	Curb Box
LOT TAP	