LABOR AND MATERIALS
ENDORMAD MATERIALS
Copper Connection\$
Curb Cock Valve In
Service Box Old returned Short 3½x4½ Long 4½x5½ Buffor Rdway
Ftin. { Copper Galv Iron Cast Iron } Pipe at\$
Nipplesin. at
Bushingstoin. at\$
Red'g Couplings to in. at
Union
Meterin. at
Lead Joints at \$
Leadite Joints at
Hrs. Chauffeur at
Hrs. Tapper at \$\$
Hrs. Labor at
Hrs. Compressor at\$
Trucking \$
Builders Use of Water\$
\$

<u>\$</u>
\$

	1 min
Grove Name of Owner	8t. Pl. Ave. No. 27
	* × * * * * * * * * * * * * * * * * * *
Labor and Mat'l. Report	AUG 2 4 1939 19
	Curb Box
Main	Elev. of Main at tap
Gate at	Gate at
3	Curb Box
8	

WATER IS 9 FEET TO THE MAIN