LABOR AND MATERIALS
Copper Connection  Cock Curb Cock In Service box Old returned Copper Bull of Rd av  Pipe at  Copper Pipe at  Service box Old returned Bull of Rd av  Pipe at  Service box Old returned Bull of Rd av  Pipe at  Service box Old returned Bull of Rd av  Service box Old returned Bull of Rd av  Service box Old returned Bull of Rd av  Service box Old returned Service box Old ret
Nipplesin. at\$
Bushingstoin. at\$
Red'g Coupl'gs to in. at \$
Union in. at \$
Meterin. at\$
Lead Joints at\$
Compound Joints at\$
Maintenance Foreman\$
Hrs. Water Maint. Man-1 at \$
Hrs. Water Maint. Man-2 at\$
Hrs. Garage Foremanat\$
Hrs. Labor—at\$
Hrs. Compressor at \$
Compensation Ins. at \$per C \$
Trucking\$
Pav't Patch\$
\$
\$
<u> </u>
O'head\$
TAP MAde By Purviste
Sept. 6-1974

Grove	St. DL Ave. No.AC
Name of Owner	Rose
Labor and Mat'l. Report	Sept 6 197
28: 9.	Curb Box - 6"
6 Main	Elev. of Main at tap
Gate at •	• Gate at
***************************************	******
	• Curb Box
¥ 15	Curb Box
7 E	Curb Box
~ E1	● Curb Box

## WATER IS 28 FEET TO THE MAIN