LABOR AND MATERIALS	
Copper Connection	<b>\$</b>
- Indeside	
Curb Valve in.	\$
(Short 3½ x 4½ )	
1 1 20112 1/2 X 0/2	\$
// 3/ [Copper]	
Ft. in. G. I. Pipe at	\$
Nipples in. at	
Bushings to in. at	\$
Red's \tnc'g \ Coupl'gstoin. at	s
Union in, at	
Meterin. at	
Lead Joints at	
Compound Joints at	
Maintenance Foreman	
Hrs. Water Maint. Man-1 at	\$
Hrs. Water Maint. Man-2 at	\$
Hrs. Garage Foremanat	\$
Hrs. Labor— at	\$
Hrs. Compressor at	\$
Compensation Ins. at \$per C	
Trucking	\$
Pav't Patch	\$
Tap by GIFFORD+Co.	\$
1 12-16-59.	\$
	\$
O'head	\$
	\$

_	
Halsey	Pl. Aver No. Z
Name of Owner	
Labor and Mat'l. Report	Dec. 16 195
22'	33'
-	Curb Box
C.T. E	Elev. of Main at tap
Gate at	• Gate at
-	• Curb Box
9	
LSM-5C-2-5 56	