LABOR AND MATERIALS	
The state of the s	
Copper Connection	s 2.71
Curb Cock Valve T.S. & V.	s 3.83
Service box Old-returned Short 3½ x 4½ Long 4½ x 5½ Buff-or-Rdway	s 469
28 Ft. Hin. Copper Pipe at 45	
Nipples in. at	e
Bushings to in. at	\$
Red'g Coupl'gs to in. at	
Unionin. at	\$
Meterin. at	\$
Lead Joints at	\$
Compound Joints at	\$
Maintenance Foreman	\$
Hrs. Water Maint, Man-1 at	S
2 Hrs. Water Maint. Man-2 at 1.24	\$ 2.48
Hrs, Garage Foreman at	\$
4 Hrs. Labor— at 1/13	· 4.C2
Hrs. Compressor at	e
Granding Index # 79	30
Compensation Ins. at \$ 4.29 per CTrucking	1.00
Trucking	\$ / 0 0
Pay't Patch	\$
Tap by gifford 6-27-55	\$^
	\$
	\$
O'head	\$
A 2 3 2 1 1 2 1 2 2 2 2 2 2 2 2 2 2 2 2 2	\$3263
STATE OF THE STATE	201
E F	
THE REAL PROPERTY.	

Harrison Ex	-St -Pl: No. 63	
Name of Owner	2 / 1	
Ti Jane.	5	
	24017	
Labor and Mat'l. Report JUNIE 27 1955		
Service of the servic		
38'		
<u>:</u>	Curb Box	
Main	Elev. of Main at tap	
Gate at •	• Gate at	
-		
• Curb Box		
B war		
.00		
1	75	
× 1	6	
L. M-5C-2-1-54	2.12, 12,	

## LABOR AND MATERIALS

Copper Connection	\$
Curb Cock Valve T.S. & V.	\$
Service box Short 3-1/2 x 4-1/2 Old returned Long 4-1/2 x 5-1/2	
$-$ Ft. $-$ in. $\left\{ egin{array}{l}  ext{Copper} \\  ext{G.l.} \\  ext{C.l.} \end{array}  ight\}$ Pipe at $ -$	\$
Nipples in. at	\$
Bushings to in. at	\$
Red'g	
Inc'g	
Union in. at	\$
Meter in. at	S
	- 2
Compound Joints at	s
Maintenance Foreman	\$
Hrs. Water Maint. Man - 1 at	\$
Hrs. Water Maint. Man - 2 at	\$
Hrs. Garage Foreman at	
Hrs. Labor at	
Hrs. Compressor at	
	020
Trucking	
Pav't Patch	0:200
	\$
4)	
	-
D 197	\$

		St.
63 1	Jarnson	Pl. Ave. No
Name of Own	ar	1
	P Johns	"Cleanas
Labor and Ma	t'l. Report 19	March 17 2015
1		1
(		1
	Encure 1	
		Pro Box
		COrb Box
		117" 1
		Flov of
M	ain Road	Main at tap
Gate at ●		Gate at
		Curb Box