

LABOR AND MATERIALS

1	Copper	} Connection ^{3/4"}	\$	
Lead				
1	Curb	} Cock	\$	
			Valve	
Same		} T.S. & V. } ^{3/4} in.	\$	
	Service box	} { Short 3 1/2 x 4 1/2	\$	
	Old returned			Long 4 1/2 x 5 1/2
				Buff or Rdway
28	Ft. ^{3/4} in.	{ Copper	\$	
		G.I.		
		C.I.		
		} Pipe at		
	Nipples	in. at	\$	
	Bushings	to in. at	\$	
	Red'g	} Coupl'gs to in. at	\$	
	Inc'g			
	Union	in. at	\$	
	Meter	in. at	\$	
	Lead Joints at		\$	
	Compound Joints at		\$	
	Maintenance Foreman		\$	
	Hrs. Water Maint. Man—1 at		\$	
	Hrs. Water Maint. Man—2 at		\$	
	Hrs. Garage Foreman at		\$	
	Hrs. Labor— at		\$	
	Hrs. Compressor at		\$	
	Compensation Ins. at \$	per C	\$	
	Trucking		\$	
	Pav't Patch		\$	
	Tap by Gifford & Co. 5-27-57		\$	
			\$	
	O'head		\$	
			\$	

St. Henry Ave. No. 39

Name of Owner Nellie Morehouse

Labor and Mat'l. Report May 27 1957

● Curb Box

6" Main Elev. of Main at tap 5'

Gate at ● ● Gate at

● Curb Box

LSM-5C-2-5 56