

### LABOR AND MATERIALS

Copper	}	Connection			\$
Lead					
Curb	{	Cock Valve T. S. & V.			\$
			in.		
Service Box	{	Short 3 1/2 x 4 1/2 Long 4 1/2 x 5 1/2 Buffer Rdway			\$
Old returned					
Ft.	}	Copper	Pipe at		\$
in.	Galv Iron				
	Cast Iron				
Nipples		in. at			\$
Bushings		to in. at			\$
Red'g Inc'g	}	Couplings	to	in. at	\$
Union		in. at			\$
Meter		in. at			\$
Lead Joints		at			\$
Leadite Joints		at			\$
Hrs. Foreman		at			\$
Hrs. Chauffeur		at			\$
Hrs. Tapper		at			\$
Hrs. Labor		at			\$
Hrs. Labor		at			\$
Hrs. Compressor		at			\$
Compensation Ins.					\$
Trucking					\$
Builders Use of Water					\$
					\$
					\$
					\$
					\$
					\$
					\$

St. \_\_\_\_\_  
 Pl. \_\_\_\_\_  
 Ave. No. 45

---

Name of Owner \_\_\_\_\_  
 TAX ID # 302.15-5-10

---

Labor and Mat'l. Report AUG 23 1939 19

● Curb Box

---

Main	Elev. of Main at tap
Gate at ●	● Gate at
● Curb Box	