

**Labor and Materials**

1	Copper } Connection	3/4	\$
1	Lead } Cock	3/4	\$
1	Curb } Valve	0.1 seal	\$
1	Service Box	Short 3' x 4'	\$
	Old returned	Long 4' x 5'	\$
		Buff. or Rdway	\$
12	Pt. 3/4 in. } Copper	Pipe at	\$
		Galv. Iron	\$
		Cast Iron	\$
	Nipples	in. at	\$
	Bushings	to in. at	\$
	Red'g } Couplings	to in. at	\$
	Inc'g		\$
	Union	in. at	\$
	Meter	in. at	\$
	Lbs. Br. Stone	at	\$
	Lbs. Sand	at	\$
	Bags Cement	at	\$
	Paving Brick	{ Mack } at	\$
		{ Red } at	\$
		{ Asphalt }	\$
	Lead Joints	at	\$
	Leadite Joints	at	\$
	Hrs. Foreman	at	\$
	Hrs. Common Labor	at	\$
	Hrs. Common Labor	at	\$
	Hrs. Mason	at	\$
	Hrs. Mason's Helper	at	\$
	Hrs. Compressor	at	\$
	Compensation Ins.		\$
	Trucking		\$
	Builders' Use of Water		\$

Tap by Donovan  
+ Hapshi 9-1-66.

Total \$

Labor and Material Report Sept. 1 1966

7 Horicon Ave.

Dr. Stokes.

Door.



6" Main

Elev. of Main at tap 5'

Gate at ●

● Gate at

● Curb Box

1  
= 0  
+  
=  
#