

Labor and Materials

1	Copper } Connection <i>3/4"</i>	\$ 3.20
	Lead }	
1	Curb { Cock Valve } <i>3/4"</i> in.	\$ 1.00
	T.S. & V. }	
1	Service Box { Short <i>3 1/2</i> x <i>4 1/2</i> }	\$ 1.40
	Old returned { Long <i>4 1/2</i> x <i>5 1/2</i> }	
	Buff. or Rdway }	
5	Pt. <i>3/4"</i> in. { Copper } Pipe at.	\$ 1.76
	Galv. Iron }	
	Cast Iron }	
	Nipples..... in. at.....	\$
	Bushings..... to..... in. at.....	\$
	Red'g } Couplings..... to..... in. at.....	\$
	Inc'g }	
	Union..... in. at.....	\$
	Meter..... in. at.....	\$
	Lbs. Br. Stone at.....	\$
	Lbs. Sand at.....	\$
	Bags Cement at.....	\$
	Paving Brick { Mack } at.....	\$
	Red }	
	Asphalt }	
	Lead Joints at.....	\$
	Leadite Joints at.....	\$
2	Hrs. Foreman at..... <i>6 2 1/2</i>	\$ 1.25
	Hrs. Common Labor at.....	\$
	Hrs. Common Labor at.....	\$
	Hrs. Mason at.....	\$
	Hrs. Mason's Helper at.....	\$
	Hrs. Compressor at.....	\$
	Compensation Ins.....	\$ <i>03</i>
	Trucking.....	\$ 1.00
	Builders' Use of Water.....	\$
Total \$		<i>9.64</i>

28-29 ~~79 Hunter~~ 113

Labor and Material Report *Apr 28* 19*28*

3/4" tap at East Hunter st

J. O'Connor

113

28' 0"

16' 10"

● Curb Box

Main

Elev. of Main at tap *4*

Gate at ●

● Gate at

● Curb Box