

LABOR AND MATERIALS

1	Copper	} Connection	3/4"	\$	
	Lead			\$	
1	Curb	} Cock Valve T.S. & V.	3/4" in.	\$	
1	Service box			} Short 3 1/2 x 4 1/2 } Long 4 1/2 x 5 1/2 }	\$
	Old returned				\$
20	Ft.	} Copper	3/4" in.	} Pipe at	\$
					} G.I.
	Nipples	in. at	\$		
	Bushings	to in. at	\$		
	Red'g	} Coupl'gs	to in. at	\$	
	Inc'g				
	Union	in. at	\$		
	Meter	in. at	\$		
			\$		
	Compound Joints	at	\$		
	Maintenance Foreman		\$		
	Hrs. Water Maint. Man—1	at	\$		
	Hrs. Water Maint. Man—2	at	\$		
	Hrs. Garage Foreman	at	\$		
	Hrs. Labor—	at	\$		
	Hrs. Compressor	at	\$		
			\$		
	Trucking		\$		
	Pav't Patch		\$		
			\$		
			\$		
			\$		
			\$		

St. KATHERINE Pt. 10 Ave. No. 10

Name of Owner FREDELLA

Labor and Mat'l. Report APR. 1926



● Curb Box

12" Main (1969) Elev. of Main at tap 5.206'

Gate at ● Gate at

TAX ID # 303.18-2-27

● Curb Box