

### LABOR AND MATERIALS

Copper	}	Connection	-----	\$
Lead				
Curb	}	Cock	-----	\$
		Valve	-----	\$
		T. S. & V.	-----	\$
Service Box	}	Short 3 1/2 x 4 1/2	-----	\$
Old returned		Long 4 1/2 x 5 1/2	-----	\$
		Buff. or Rdway	-----	\$
Ft. _____ in.	}	Copper	} Pipe at	-----
		Galv Iron		-----
		Cast Iron		-----
Nipples _____ in.	at	-----	\$	
Bushings _____ to _____ in.	at	-----	\$	
Red'g } Couplings _____ to _____ in.	at	-----	\$	
Inc'g }				
Union _____ in.	at	-----	\$	
Meter _____ in.	at	-----	\$	
Lead Joints	at	-----	\$	
Leadite Joints	at	-----	\$	
Hrs. Foreman	at	-----	\$	
Hrs. Chauffeur	at	-----	\$	
Hrs. Tapper	at	-----	\$	
Hrs. Labor	at	-----	\$	
Hrs. Labor	at	-----	\$	
Hrs. Compressor	at	-----	\$	
Compensation Ins.		-----	\$	
Trucking		-----	\$	
Builders Use of Water		-----	\$	
		-----	\$	
		-----	\$	
		-----	\$	
		-----	\$	

99-26  
20A13  
 St: \_\_\_\_\_  
 Pt: \_\_\_\_\_  
 Ave. No. 18

Kenworthy

**Name of Owner** \_\_\_\_\_

---

**Labor and Mat'l. Report** Aug. 18 1939

20A13  

● Curb Box

---

Main	Elev. of Main at tap _____
Gate at ●	● Gate at

---

● Curb Box

27' 6" 17' 5"