LABOR AND MATERIALS	5
Copper Connection Cock	_ \$
Curb Valve in.	\$
Old returned Buff or Rdway	\$
Ft. in. Copper Pipe at G. I.	_ \$
Nipples in, at	\$
Bushings to in, at	_ \$
Red'g	
Inc'g \rightarrow Coupl'gstoin. at	
Unionin, at	
Meterin, at	
Lead Joints at	\$
Compound Joints at	_ \$
Maintenance Foreman	\$
Hrs. Water Maint. Man-1 at	_ \$
Hrs. Water Maint. Man-2 at	\$
Hrs. Garage Foremanat	\$
Hrs. Laborat	_ S
Hrs. Compressor at	S
Compensation Ins. at \$per C_	
Trucking	
Pay't Patch	_ S
10050100 112 514	_ S
DAMPSON F COL	S .
	- \$ - \$
_ O'head 8 - 12 - 66	\$
UESU	
	\$

Knight	St. Pl: Ave. No.
Name of Owner	
Labor and Mat'l. Report	197
2 101	© Curb Box
Main	Elev. of Main at tap
Gate at	• Gate at
	• Curb Box
sM—8C3-10-61	