

**Labor and Materials**

Copper } Connection.....	3	\$ 320
Lead } .....	1	
Curb } Cock } .....	1	\$ 1.00
Valve } T. S. & V. } .....	1	
Service Box } Short 3" x 4" } .....	1	\$ 1.30
Old <del>Service Box</del> } Long 4" x 6" } .....	1	
Buff. or Rdway } .....	1	
24 Ft. } in. } Copper } Pipe at.....	24	\$ 128
Galv. Iron } Cast Iron } .....		
Nipples.....	in. at.....	\$
Bushings.....	to..... in. at.....	\$
Red'g } Couplings.....	to..... in. at.....	\$
Inc'g } .....		
Union.....	in. at.....	\$
Meter.....	in. at.....	\$
Lbs. Br. Stone at.....		\$
Lbs. Sand at.....		\$
Bags Cement at.....		\$
Paving Brick } Mack } at.....		\$
Red } Asphalt } .....		
Lead Joints at.....		\$
Leadite Joints at.....		\$
2 Hrs. Foreman at.....		\$ 1.25
3 Hrs. Common Labor at.....		2.93
Hrs. Common Labor at.....		\$
Hrs. Mason at.....		\$
Hrs. Mason's Helper at.....		\$
Hrs. Compressor at.....		\$
Compensation Ins.....		\$ .87
Trucking.....		\$ 1.50
Builders' Use of Water.....		\$ 1.50
Total \$		6.65

**Labor and Material Report**

19

24 REC: 5  
53 LaRose St. McHenry



● Curb Box

6 Main Elev. of Main at tap 4 1/2  
Gate at ● Gate at ●

● Curb Box

OUTSIDE c/o  
INSTALLED 11/24/2008