

LABOR AND MATERIALS

1 Copper } Connection <sup>3/4"</sup> ----- \$  
~~Lead~~

1 Curb { Cock Valve } ----- in. ----- \$  
 T. S. & V.

1 Service Box { Short 3/2x4 1/2 } ----- \$  
 Old returned { Long 4 1/2x5 1/2 }  
 Buff. or Rdway

6 <sup>3/4</sup> Ft. <sup>3/4</sup> in. { Copper } Pipe at ----- \$  
 { Galv Iron }  
 { Cast Iron }

Nipples ----- in. at ----- \$

Bushings ----- to ----- in. at ----- \$

Red'g } Couplings ----- to ----- in. at ----- \$  
 Inc'g }

Union ----- in. at ----- \$

Meter ----- in. at ----- \$

Lead Joints at ----- \$

Leadite Joints at ----- \$

Hrs. Foreman at ----- \$

Hrs. Chauffeur at ----- \$

Hrs. Tapper at ----- \$

Hrs. Labor at ----- \$

Hrs. Labor at ----- \$

Hrs. Compressor at ----- \$

Compensation Ins. ----- \$

Trucking ----- \$

Builders Use of Water ----- \$

Tap by Lareau & Co. ----- \$  
 7-18-58 ----- \$  
 ----- \$  
 ----- \$  
 ----- \$

✓

St. <sup>56</sup>  
~~Pl.~~  
 Ave. No. <sup>48</sup>

Lawrence

Name of Owner Orsini

Labor and Mat'l. Report July 18 1958

56

● Curb Box

12" Main Elev. of Main at tap <sup>4'</sup>

Gate at ● ● Gate at

TAX ID # 303.17-3-13

● Curb Box