

Labor and Materials

1	Copper Lead	Connection - 3/4"	\$ 1.46
1	Curb	Cock Valve T. S. & V. 3/4" in	\$ 1.93
1	Service Box Old returned	Short 3 1/2 x 4 1/2 Long 4 1/2 x 5 1/2 Buff. or Rdway	\$ 1.77
7	Ft. 3/4" in.	Copper Galv-Iron Cast Iron Pipe at 22	\$ 1.54
	Nipples	in. at	\$
	Bushings	to in. at	\$
	Red'g Inc'g	Couplings to in. at	\$
	Union	in. at	\$
	Meter	in. at	\$
	Lead Joints	at	\$
	Leadite Joints	at	\$
	Hrs. Foreman	at	\$
2	Hrs. Chauffeur	at 62 1/2	\$ 1.25
9	Hrs. Tapper	at 62 1/2	\$ 5.63
8	Hrs. Labor	at 45	\$ 3.60
	Hrs. Labor	at	\$
2	Hrs. Compressor	at 87 1/2	\$ 1.75
	Compensation Ins.		\$ 32
	Trucking		\$ 1.00
	Builders Use of Water		\$ 9.00
			\$
			\$
			\$
	Tap made by Rens		\$
			\$ 29.25

29-1937

St. *58*
 Pt. *Lawrence*
 Ave. No. *820*

Name of Owner
Lucio Pizzello

Labor and Mat'l. Report *June 12* 19*37*

TAX ID # 303.17-3-14.1

12' Main Elev. of Main at tap *4 1/2*

Gate at ● ● Gate at

● Curb Box
Old tap shut off

ff