

LABOR AND MATERIALS

1	Copper Lead	Connection	3/4"	\$	308
1	Curb	Cock Valve T. S. & V.	3/4 in.	\$	389
1	Service box	Short 3 1/2 x 4 1/2		\$	
	Old returned	Long 3 1/2 x 5 1/2		\$	
		Buff. or Rdway		\$	
6	Ft. 3/4 in.	Copper G.I. Pipe at	45	\$	270
	Nipples	in. at		\$	
	Bushings	to in. at		\$	
	Red'g Inc'g	Coupl'gs to in. at		\$	
	Union	in. at		\$	
	Meter	in. at		\$	
	Lead Joints at			\$	
	Compound Joints at			\$	
	Maintenance Foreman			\$	32.17
	Hrs. Water Maint. Man-1 at			\$	
4	Hrs. Water Maint. Man-2 at	1.613		\$	6.45
4	Hrs. Garage Foreman	1.481		\$	5.92
16	Hrs. Labor	at 1.30		\$	20.80
	Hrs. Compressor at			\$	
	Compensation Ins. at \$5.686 per C			\$	1.89
	Trucking			\$	150
	Pay't Patch	Before Paving		\$	
		Tap made Aug 14, 56		\$	
		By Gifford & Thomas		\$	
	O'head			\$	
				\$	46.24

2022 - 80 Lawrence: copper on our side; galv on homeowner's

St. Lawrence
Pr. Ave. No. 80
82

Name of Owner Fusco

Labor and Mat'l. Report Aug 14 1956

17" Main Elev. of Main at tap 5'

Gate at ● ● Gate at

● Curb Box

ay

L M-5C-2-1-54