

LABOR AND MATERIALS

1	Copper	} Connection <sup>3/4"</sup>	\$	_____	
1	Lead				
1	Curb	} Cock Valve T.S. & V.	in.	\$ _____	
1	Service box		} Short 3 1/2 x 4 1/2 Long 4 1/2 x 5 1/2		\$ _____
	Old returned				
26	Ft.	} Copper G.I. G.I.	} Pipe at	\$ _____	
	3/4 in.				
	Nipples	in.	at	\$ _____	
	Bushings	to	in.	at \$ _____	
	Red'g Inc'g	} Coupl'gs	to	in.	at \$ _____
	Union		in.	at	\$ _____
	Meter	in.	at	\$ _____	
	Compound Joints	at \$ _____			
	Maintenance Foreman	at \$ _____			
	Hrs. Water Maint. Man-1	at \$ _____			
	Hrs. Water Maint. Man-2	at \$ _____			
	Hrs. Garage Foreman	at \$ _____			
	Hrs. Labor	at \$ _____			
	Hrs. Compressor	at \$ _____			
	Trucking	\$ _____			
	Pay't Patch	\$ _____			
		\$ _____			
		\$ _____			
		\$ _____			

REAR OF 201 BAY

LEXINGTON

St. \_\_\_\_\_  
Pl: \_\_\_\_\_  
Ave. No. 1/2

Name of Owner \_\_\_\_\_

Labor and Mat'l. Report

SEPT. 19 25

GARAGE

33' 4/0'S"

● Curb Box

6" Main

Elev. of Main at tap 6'

Gate at ●

● Gate at

● Curb Box

TAP ON LEXINGTON