

LABOR AND MATERIALS

Copper	} Connection	\$	
Lead		\$	
Curb	} Clock Valve T. S. & V. in.	\$	
Service box		} Short 3½X4½ Long 4½X5½ Buff or Rdway	\$
Old returned		\$	
Ft. in.	} Copper Galv. Iron Cast Iron		Pipe at	\$
Nipples	 in. at	\$	
Bushings to	in. at	\$	
Red'g Inc'g	} Couplings to	in. at	\$
Union	 in. at	\$	
Meter in. at	\$		
Lead Joints at	\$		
Compound Joints at	\$		
Hrs. Foreman at	\$		
Hrs. Chauffeur at	\$		
Hrs. Tapper at	\$		
Hrs. Labor at	\$		
Hrs. Labor at	\$		
Hrs. Compressor at	\$		
Compensation Ins.	\$		
Trucking	\$		
Builders Use of Water	\$		
<i>Warkuliska</i>	\$		
.....	\$		
.....	\$		
.....	\$		
.....	\$		
.....	\$		

St. **73**
Pl. **73**
Ave. No. **51**

Lexington

Name of Owner

Labor and Mat'l. Report *June* 19*45*

#51
73

● Curb Box

Main	Elev. of Main at tap
Gate at ●	● Gate at

● Curb Box