

### LABOR AND MATERIALS

1	Copper } Connection	$\frac{3}{4}$ "			\$
	Lead				
1	Curb { Clock Valve	$\frac{3}{4}$	in.		\$
	(T. S. & V.)				
1	Service box	Short $3\frac{1}{2}$ X $4\frac{1}{2}$ Long $4\frac{1}{2}$ X $5\frac{1}{2}$ Buff or Rdway			\$
	Old returned				
26	Ft. $\frac{3}{4}$ in.	Copper } Pipe at			\$
		Galv. Iron }			
		Cast Iron }			
	Nipples	in. at			\$
	Bushings	to in. at			\$
	Red'g } Couplings	to in. at			\$
	Inc'g }				
	Union	in. at			\$
	Meter	in. at			\$
	Lead Joints at				\$
	Compound Joints at				\$
	Hrs. Foreman at				\$
	Hrs. Chauffeur at				\$
	Hrs. Tapper at				\$
	Hrs. Labor at				\$
	Hrs. Labor at				\$
	Hrs. Compressor at				\$
	Compensation Ins.				\$
	Trucking				\$
	Builders Use of Water				\$
	Measure by Meters				\$
	Found Copper by				\$
	Lareau Co. 4-5-71.				\$
					\$

St. Liberty  
 Pl. #1  
 Ave. No.

Name of Owner \_\_\_\_\_

---

*Due to leak at main Found  
Labor and Mat'l. Report to be Copper 4/5 19 71*

---

	Main	Elev. of Main at tap _____
Gate at ●		● Gate at

---

L. 21' 11"
● Curb Box  

R. 55"

LSM-5C-6-1-45