

Labor and Materials

Copper	} Connection.....	\$			
Lead						
Curb	} Cock Valve } T. S. & V. }	in	\$			
Service Box				} Short 3½ x 4½ } Long 4½ x 5½ }	\$
Old returned						
Ft.in.	} Copper } Galv Iron } Cast Iron }	Pipe at	\$			
Nipples				in. at	\$	
Bushings	to	in. at	\$			
Red'g } Inc'g }	} Conplings.....to	in. at	\$			
Union				in. at	\$	
Meter	in. at	\$				
Lead Joints at	\$					
Leadite Joints at	\$					
Hrs. Foreman at	\$					
Hrs. Chauffeur at	\$					
Hrs. Tapper at	\$					
Hrs. Labor at	\$					
Hrs. Labor at	\$					
Hrs. Compressor at	\$					
Compensation Ins.	\$					
Trucking	\$					
Builders Use of Water	\$					
.....	\$					
.....	\$					
.....	\$					
.....	\$					
.....	\$					
.....	\$					
.....	\$					

Lincoln St. Ave. No. 16
Pl.

Name of Owner
Ellsworth

Labor and Mat'l. Report 4-11-21 19

16 Main Elev. of Main at tap 3½

Gate at • • Gate at

TAX ID # 302.15-13-5

● Curb Box