

Labor and Materials

3	Copper } Connection	1	\$ 3.20
24	Lead } Cock	3	1.00
24	Curb } Valve	3	
		in.	
		F. S. & V.	
1	Service Box } Short 3 1/2 x 4 1/2		1.30
	Old returned } Long 4 1/2 x 5 1/2		
		Buff. or Rdway	
37	Ft. in. } Copper		8.14
		Galv. Iron	
		Cast Iron	
	Pipe at		
	Nipples	in. at	
1	Bushings	3 to 3 in. at	0.8
1	Red g. Inc'g } Couplings	3 to 3 in. at	1.5
	Union	in. at	
	Meter	in. at	
	Lbs. Br. Stone at		
	Lbs. Sand at		
	Bags Cement at		
	Paving Brick } (Mack		
		Red	
		Asphalt)	
	Lead Joints at		
	Leadite Joints at		
4	Hrs. Foreman at	62.5	2.50
5	Hrs. Common Labor at	50	2.50
19	Hrs. Common Labor at	37	7.70
	Hrs. Mason at		
	Hrs. Mason's Helper at		
	Hrs. Compressor at		
	Compensation Ins.		34
1	Trucking		1.00
	Builders' Use of Water		
Total			\$ 27.91

26-93

Labor and Material Report

1910

July 31

7 Lincoln St

Road

Porch

26' 9"

5-074

● Curb Box 40' 5"

165 Main

Elev. of Main at tap 5 1/4

● Gate at ● Gate at

● Curb Box