

LABOR AND MATERIALS

/	Copper Lead	} Connection $\frac{3}{4}$			\$
/	Curb	} Cock Valve T.S. & V.	$\frac{3}{4}$ in.		\$
/	Service Box Old returned	} Short $3\frac{1}{2} \times 4\frac{1}{2}$ Long $4\frac{1}{2} \times 5\frac{1}{2}$ Buff for Rdway			\$
24	Ft.	$\frac{3}{4}$ in.	} Copper Galv-Iron Cast-Iron	Pipe at	\$
	Nipples	in. at			\$
	Bushings	to in. at			\$
	Red'g Inc'g	} Couplings	to in. at		\$
	Union	in. at			\$
	Meter	in. at			\$
	Lead Joints at				\$
	Leadite Joints at				\$
	Hrs. Foreman at				\$
	Hrs. Chauffeur at				\$
	Hrs. Tapper at				\$
	Hrs. Labor at				\$
	Hrs. Labor at				\$
	Hrs. Compressor at				\$
	Compensation Ins.				\$
	Trucking				\$
	Builders Use of Water				\$
	Tap by <i>Waxmins. Inc.</i>				\$
					\$
	<i>1. Hole 6 X 3</i>				\$
					\$

St. 15
 Pt.
 Ave. No. 11

Locust

Name of Owner
Bromley

Labor and Mat'l. Report *June 5* 1945

Back Porch

Maple St

Locust St

Curb Box

6601 Main

Elev. of Main at tap 5

Gate at ● Gate at

● Curb Box

This tap on Maple St