

**Labor and Materials**

Lead Connection .....	\$
4 Curb Cock .....	\$
Service Box (Short 3' x 4')	\$
Old returned (Long 4' x 5')	\$
30 Buffalo	\$
30 Ft. in. G. I. Pipe at <i>Copper</i>	\$
Nipples .....	\$
Bushings .....	\$
1 Red'g Coup 3" to 1" in. at	\$
1 Inc'g Coup to in. at	\$
1 Union in. at 1" to 1"	\$
Meter .....	\$
Cu. Yds. Br. Stone at	\$
Cu. Yds. Sand at	\$
Bags Cement at	\$
Paving Brick (Mack Red Asphalt) at	\$
7 Hrs. Foreman at	\$
11 Hrs. Common Labor at	\$
Hrs. Mason at	\$
Hrs. at	\$
Hrs. at	\$
for Builders' Use of Water	\$
Truck 100	\$
at	\$
at	\$
at	\$
Total	\$

Labor and Material Report

Oct 20 19 20

3/4" 16 Locust



Main Elev. of Main at tap

Gate at ● ● Gate at

● Curb Box

*Dug up & Found to Be Copper 11/8/76*