

### LABOR AND MATERIALS

1	Copper	} Connection	<u>3/4</u>		\$
	Lead				
1	Curb	} Cock			
		} Valve	<u>3/4</u> in.		\$
		} T. S. & V.			
<i>Same</i>	Service box	}	Short $3\frac{1}{2} \times 4\frac{1}{2}$		
	Old returned		Long $4\frac{1}{2} \times 5\frac{1}{2}$		
			Buff or Rdway		\$
10	Ft. <u>3/4</u> in.	{ Copper	}	Pipe at	\$
		{ G. I.			
		{ C. I.			
	Nipples	in. at			\$
	Bushings	to in. at			\$
	Red'g	}			
	Inc'g				
	Coupl'gs	to in. at			\$
	Union	in. at			\$
	Meter	in. at			\$
	Lead Joints at				\$
	Compound Joints at				\$
	Maintenance Foreman				\$
	Hrs. Water Maint. Man-1 at				\$
	Hrs. Water Maint. Man-2 at				\$
	Hrs. Garage Foreman at				\$
	Hrs. Labor at				\$
	Hrs. Compressor at				\$
	Compensation Ins. at \$	per C			\$
	Trucking				\$
	Pav't Patch				\$
	<i>Tap by Gifford &amp; Co. 7-60</i>				
	O'head				\$

St. \_\_\_\_\_  
 Pt. \_\_\_\_\_  
 Ave. No. 19

Logan

Name of Owner \_\_\_\_\_

---

July 26 1960

Labor and Mat'l. Report

23' 9"      27'

● Curb Box

6" Main
Elev. of Main at tap 5'

Gate at ●
● Gate at

28' 4"      25' 7"

● Curb Box      OUTSIDE PAVEMENT

LSM-SC-2-5-56