

### LABOR AND MATERIALS

Copper	}	Connection		\$	
Lead					
Curb	}	Cock	in.		\$
		Valve			
		T. S. & V.			
Service box	}	Short 3½ x 4½			\$
Old returned		Long 4½ x 5½			
		Buff or Rdway			
Ft.	}	Copper	in.		\$
		G. I.			
		C. I.			
		Pipe at			
Nipples		in. at			\$
Bushings		to in. at			\$
Red'g	}	Coupl'gs			\$
Inc'g					
Union		in. at			\$
Meter		in. at			\$
Lead Joints		at			\$
Compound Joints		at			\$
Maintenance Foreman					\$
Hrs. Water Maint. Man—1		at			\$
Hrs. Water Maint. Man—2		at			\$
Hrs. Garage Foreman		at			\$
Hrs. Labor		at			\$
Hrs. Compressor at					\$
Compensation Ins. at \$		per C			\$
Trucking					\$
Pav't Patch					\$
					\$
					\$
					\$
O'head					\$

St.  
 Pl.  
 Ave. No. **49**

*McARTHUR*

---

Name of Owner \_\_\_\_\_

---

Labor and Mat'l. Report 19

---

---

\_\_\_\_\_ Main

Gate at ●

Elev. of Main at tap \_\_\_\_\_

● Gate at

---

*COPPER LINE* ● Curb Box