

LABOR AND MATERIALS

1	Copper	Connection	3/4"		\$
1	Lead	Cock	3/4 in.		\$
1	Curb	Valve			\$
		T. S. & V.			\$
1	Service box	}	Short 3 1/2 x 4 1/2		\$
	Old returned		Long 4 1/2 x 5 1/2		\$
			Buff or Rdway		\$
17	3/4 in.	Copper	}	Pipe at	\$
		G. I.			\$
		C. I.			\$
	Nipples	in. at			\$
	Bushings	to in. at			\$
	Red'g	}	Coupl'gs	to in. at	\$
	Inc'g				
	Union	in. at			\$
	Meter	in. at			\$
	Lead Joints	at			\$
	Compound Joints	at			\$
	Maintenance Foreman				\$
	Hrs. Water Maint. Man	—1 at			\$
	Hrs. Water Maint. Man	—2 at			\$
	Hrs. Garage Foreman	at			\$
	Hrs. Labor	at			\$
	Hrs. Compressor	at			\$
	Compensation Ins.	at \$ per C			\$
	Trucking				\$
	Pay't Patch				\$
	Top by Gifford & Co.				\$
	1-5-59				\$
	O'head				\$

St. Dir.
Pl: Ave. No. 55

MacArthur

Name of Owner
William R. Washburn

Labor and Mat'l. Report Jan. 5 1959

Elev. of Main at tap 5 1/2'

Gate at ● ● Gate at

● Curb Box

LSM-5C-2.5 56