

LABOR AND MATERIALS

1. Copper Lead Connection $3/4$	\$ 2.94
1. Curb Valve T.S. & V. $3/4$ in.	\$ 3.71
1. Service box Old returned	\$ 5.90
25. Ft. $3/4$ in. Copper G.I. C.I. Pipe at 30	\$ 7.50
Nipples in. at	\$
Bushings to in. at	\$
Red'g Inc'g Coupl'gs to in. at	\$
Union in. at	\$
Meter in. at	\$
Lead Joints at	\$
Compound Joints at	\$
1. Hrs. Water Maint. Man-1 at	\$
5. Hrs. Water Maint. Man-2 at 91	\$ 4.55
18. Hrs. Labor- at 20	\$ 14.40
Hrs. Labor- at	\$
Hrs. Compressor at	\$
Compensation Ins. at \$ per C.	\$ 42
Trucking	\$ 1.00
Pav't Patch	\$
Tap by <i>Tap by [Signature]</i>	\$
O'head	\$
	\$ 40.42

46 # 21

St. *1st*  
Pl. *83*  
Ave. No.

Name of Owner *C. Lymann*

Labor and Mat'l. Report *July 30* 19*48*

40'4" 41'6" Curb Box

*12* Main Elev. of Main at tap *5*

Gate at ● Gate at ●

● Curb Box

LBM-5C 5 15-48