

Labor and Materials

Copper	}	Connection.....	\$
Lead			\$
Curb	}	Cock Valve T. S. & V. }	in
			\$
Service Box Old returned	}	Short $3\frac{1}{2} \times 4\frac{1}{2}$	\$
		Long $4\frac{1}{2} \times 5\frac{1}{2}$	
		Buff. or Rdway	
Ft.	}	Copper	Pipe at
in.		Galv Iron	
		Cast Iron	
Nipples	in. at	\$	
Bushings	to	\$	
Red'g Inc'g	}	Conplings..... to	in. at
		\$	
Union.....	in. at	\$	
Meter.....	in. at	\$	
Lead Joints at	\$		
Leadite Joints at	\$		
Hrs. Foreman at	\$		
Hrs. Chauffeur at	\$		
Hrs. Tapper at	\$		
Hrs. Labor at	\$		
Hrs. Labor at	\$		
Hrs. Compressor at	\$		
Compensation Ins.	\$		
Trucking	\$		
Builders Use of Water	\$		
	\$		
	\$		
	\$		
	\$		
	\$		
	\$		
	\$		
	\$		
	\$		
	\$		
	\$		
	\$		
	\$		
	\$		
	\$		
	\$		
	\$		
	\$		
	\$		
	\$		
	\$		
	\$		

St.
 Pl.
 Ave. No. 36

Maple

Name of Owner
First National Bank
Drive-in

Labor and Mat'l. Report 19

Building Razed.

36-11

Curb Box

Now Used for Hose Connection
FIRST NATIONAL BANK PROPERTY

Elev. of
Main at tap 2.70

.....Main

Gate at ● Gate at

● Curb Box

1 - Buffalo box
shut off at curb.

1 - Regular box used
For Hose Conn.