

Labor and Materials

Copper	Lead	Connection	\$ 2.70
Curb	Cock Valve	T.S. & V. in.	\$ 2.81
Service Box	Short 3 1/2 x 4 1/2	Long 4 1/2 x 5 1/2	Buff. or Rdway	\$ 1.45
Old returned	Copper Galv-Iron	Cast-Iron	Pipe at	\$ 6.48
2 1/2 Ft.	in.	in. at		\$
Nipples	in.	in. at		\$
Bushings	to	in. at		\$ 1.0
Red'g Inc'g	Couplings	to	in. at	\$
Union	in.	at		\$
Meter	in.	at		\$
Lbs. Br. Stone	at			\$
Lbs. Sand	at			\$
Bags Cement	at			\$
Paving Brick	Mack Red Asphalt	at		\$
Lead Joints	at			\$
Leadite Joints	at			\$
4 Hrs.	Foreman	at		\$ 2.50
1 Hrs.	Common-Labor	at	Tapper @ .50	\$.50
15 1/2 Hrs.	Common Labor	at		\$ 6.98
Hrs.	Mason	at		\$
Hrs.	Mason's Helper	at		\$
Hrs.	Compressor	at		\$
Compensation	Ins			\$.31
Trucking				\$ 1 -
Builders' Use of Water	Pitch			\$ 25 -
Total \$				49.41

30-190

Labor and Material Report

1920

143 Maple Street



TAX ID # 303.17-18-7

Main

Elev of Main at tap

Gate at

24' to MAIN

Gate at

Curb Box

old tap disconnected