

LABOR AND MATERIALS

Copper } Connection		\$
Lead } {		
Curb } Cock		
} Valve	in.	\$
} T. S. & V.		
Service box } Short 3½ x 4½		
Old returned } Long 4½ x 5½		\$
Ft. 3/4 in. } Copper	Pipe at	\$
} G.I.		
} G.I.		
Nipples	in. at	\$
Bushings	to in. at	\$
Red'g } Coupl'gs	to in. at	\$
Inc'g }		
Union	in. at	\$
Meter	in. at	\$
		\$
Compound Joints at		\$
Maintenance Foreman		\$
Hrs. Water Maint. Man-1 at		\$
Hrs. Water Maint. Man-2 at		\$
Hrs. Garage Foreman at		\$
Hrs. Labor at		\$
Hrs. Compressor at		\$
		\$
Trucking		\$
Pav't Patch		\$
		\$
		\$
		\$
		\$
		\$

MAPLE

St. Pt. Ave. No. 212

Name of Owner

MONTERO

Labor and Mat'l. Report

19 94



Main

Elev. of Main at tap

Gate at ●

● Gate at

● Curb Box

TAX ID # 303.17-14-19