

Labor and Materials		\$.
Lead Connection	3	\$.
Curb Cock	4	\$.
Service Box	Short 3½ x 4½	\$.
Old returned	Buffalo	\$.
Ft. in. G. I. Pipe at		\$.
Nipples	in. at	\$.
Bushings	to in. at	\$.
Red'g Coup	to in. at	\$.
Inc'g Coup	to in. at	\$.
Union	in. at	\$.
Meter	in. at	\$.
Cu. Yds. Br. Stone at		\$.
Cu. Yds. Sand at		\$.
Bags Cement at		\$.
Paving Brick	{ Mack Red Asphalt } at	\$.
Hrs. Foreman at	2	\$.
Hrs. Common Labor at	9	\$.
Hrs. Mason at		\$.
Hrs.	at	\$.
Hrs.	at	\$.
Builders' Use of Water		\$.
Truck	100	\$.
	at	\$.
	at	\$.
	at	\$.
	at	\$.
Total		\$ 12.30

7 May 13 1928

Labor and Material Report

7 Main Ave

Diagram description: A trapezoidal shape representing a curb box. The top horizontal edge is 24' 9". The bottom horizontal edge is 21' 4". The left slanted edge is labeled 32' and the right slanted edge is labeled 30'. A solid black circle at the bottom center is labeled 'Curb Box'.

Ben. Gabor and Sons

4 Main Elev. of Main at tap 4½

Gate at 9' to main Gate at

1" GAL. Curb Box

TAX ID #302.20-7-7