

### Labor and Materials

1	Copper	} Connection $\frac{1}{2}$ "	\$
	Lead		
1	Carb	} Cock Valve } $\frac{5}{8}$ in	\$
			T-S. & V.
1	Service Box	} Short $3\frac{1}{2} \times 4\frac{1}{2}$	\$
4'	Old returned		Long $4\frac{1}{2} \times 5\frac{1}{2}$
			Buff. or Rdway
	4' Ft. <del>1</del> " in.	} Copper } Pipe at	\$
			Galv-iron } Cast-iron }
	Nipples	in. at	\$
	Bushings	to in. at	\$
	Red'g	} Couplings	\$
	Inc'g		to in. at
	Union	in. at	\$
	Meter	in. at	\$
	Lead Joints	at	\$
	Leadite Joints	at	\$
	Hrs. Foreman	at	\$
	Hrs. Chauffeur	at	\$
	Hrs. Tapper	at	\$
	Hrs. Labor	at	\$
	Hrs. Labor	at	\$
	Hrs. Compressor	at	\$
	Compensation Ins.		\$
	Trucking		\$
	Builders Use of Water		\$
			\$
			\$
			\$
			\$
			\$

St. 18  
Pr. 12  
Ave. No. 12

*May*

Name of Owner \_\_\_\_\_

---

Labor and Mat'l. Report July 2 1985

18

40-10 30-0

● Curb Box

---

8 1976 Main Elev. of Main at tap \_\_\_\_\_

Gate at ● \_\_\_\_\_ ● Gate at \_\_\_\_\_

---

● Curb Box

Tax Map # 302.20-10-20

*Renewal Days*

*Fall 1986*