

Labor and Materials

Copper	Connection	\$ 1.50	
Curb	Cock Valve in	\$ 1.70	
			
Service Box	Old returned	Short $2\frac{1}{2} \times 1\frac{1}{2}$	\$ 1.54	
		Long $4\frac{1}{2} \times 5\frac{1}{2}$		
31 Ft.	in.	Copper	Pipe at	\$ 5.89
		Galv. Iron		
		Cast Iron		
		Nipples	in. at	\$
		Bushings	to .. in. at	\$
		Red'g Inc'g	Couplings to .. in. at	\$
		Union	in. at	\$
		Meter	in. at	\$
		Lbs. Br. Stone	at	\$
		Lbs. Sand	at	\$
		Bags Cement	at	\$
		Paving Brick	at	\$
				Mack Red Asphalt
		Lead Joints	at	\$
		Leadite Joints	at	\$
7	Hrs.	Foreman	at	\$ 4.38
4	Hrs.	Common Labor	at	\$ 2.00
22	Hrs.	Common Labor	at	\$ 9.90
	Hrs.	Mason	at	\$
	Hrs.	Masons Helper	at	\$
	Hrs.	Compressor	at	\$
		Compensation Ins		\$ 0.58
		Trucking		\$ 3.00
		Builders Use of Water	Paint Patch	\$ 5.00
Total \$				35.49

92 34 42
Labor and Material Report *Sept 18* 1934

34 McDonald St

Curb Box

8"-1975 Main Elev. of Main at tap *6 1/2*

Gate at TAX ID # 303.18-5-6 Gate at

Curb Box

old trap to be dug up to be paid for.

HWS