

LABOR AND MATERIALS

.....	Copper	Connection.....	\$.....
.....	Lead	.....	\$.....
.....	Curb	Cock Valve T. S. & V. in.....	\$.....
.....	Service box	Short $3\frac{1}{2} \times 4\frac{1}{2}$	\$.....
.....	Old returned	Long $4\frac{1}{2} \times 5\frac{1}{2}$	
.....		Buff or <del>Redway</del>	
.....	Ft.....	in. <del>C.I.</del> Copper Pipe at.....	\$.....
.....	Nipples.....	in. at.....	\$.....
.....	Bushings.....	to..... in. at.....	\$.....
.....	Red'g	Inc'g Coupl'gs..... to..... in. at.....	\$.....
.....	Union.....	in. at.....	\$.....
.....	Meter.....	in. at.....	\$.....
.....	Lead Joints at.....		\$.....
.....	Compound Joints at.....		\$.....
.....	Hrs. Water Maint. Man—1 at.....		\$.....
.....	Hrs. Water Maint. Man—2 at.....		\$.....
.....	Hrs. Labor—.....	at.....	\$.....
.....	Hrs. Labor—.....	at.....	\$.....
.....	Hrs. Compressor at.....		\$.....
.....	Compensation Ins. at \$.....	per C.....	\$.....
.....	Trucking.....		\$.....
.....	Pav't Patch.....		\$.....
.....	O'head.....		\$.....
.....			\$.....

St.  
Pl.—  
Ave. No. 10

Monroe

Name of Owner \_\_\_\_\_

---

Labor and Mat'l. Report July 29 1949

..... Main Elev. of Main at tap.....

Gate at ● ● Gate at

● Curb Box

Tax ID # 302.16-11-21

LGM-5C 8 15-48 Buff Hole Box