

Labor and Materials

1	Copper	} Connection <i>3/4"</i>		\$	
	Lead				
1	Curb	} Cock Valve <i>3/4</i> in		\$	
			T. S. & V.		
1	Service Box	} Short <i>3 1/2 x 4 1/2</i>		\$	
	Old returned		Long <i>4 1/2 x 5 1/2</i>		
		Buff. or Rdway			
7	Ft. <i>3/4</i> in.	} Copper Galv Iron Cast Iron	Pipe at	\$	
	Nipples			in. at	\$
	Bushings			To in. at	\$
	Red'g	} Conplings			
	Inc'g			to in. at	\$
	Union		in. at	\$	
	Meter		in. at	\$	
	Lead Joints		at	\$	
	Leadite Joints		at	\$	
	Hrs. Foreman		at	\$	
	Hrs. Chauffeur		at	\$	
	Hrs. Tapper		at	\$	
	Hrs. Labor		at	\$	
	Hrs. Labor		at	\$	
	Hrs. Compressor		at	\$	
	Compensation Ins.			\$	
	Trucking			\$	
	Builders Use of Water			\$	
	<i>Tap by Lareau & Co.</i>			\$	
	<i>6-8-66</i>			\$	
				\$	
				\$	
				\$	

St. *Montclair*
Pk. *11*
Ave. No. *11*

Name of Owner
Robert Belter

Labor and Mat'l. Report *June 12* 19*66*

37'-2" 29'-6" 29'-6"

● Curb Box

10 Main Elev. of Main at tap *5*

Gate at ● ● Gate at

● Curb Box

Tax ID # 309.27-2-25