## LABOR AND MATERIALS

Copper Connection	\$
Cock	
Service box Old returned Short 3½ x 4½ Long 4½ x 5½ Buff or Rdway Copper Copper	
25 Ft. 94 in. Copper Spipe at	\$
Nipplesin. at	. \$
Bushings to in at	\$
Red'g Coupl'gstoin. at	
Unionin. at	- \$
Meter in, at	. \$
Lead Joints at	. \$
Compound Joints at	. s
Maintenance Foreman	S
Hrs. Water Maint. Man-1 at	S
Hrs. Water Maint, Man-2 at	
Hrs. Garage Foreman at	14700
Hrs. Labor— at	1990
Hrs. Compressor at	
Compensation Ins. at \$per C	
	. S
Pav't Patch	
	- 5
·	. \$
	. \$
O'head	- <u>\$</u>
	\$

MONTCALM	St. PI. Ave. No. 20
Name of Owner	
	^
Labor and Mat'l. Report	19
D. H.	Curb Box
Main	Elev. of Main at tap
Gate at •	• Gate at
	Curb Box
REMEASU	
NEWN	1. FASURMENTS
TOV 10# 30	9.27-6-33