

LABOR AND MATERIALS

1	Copper	Connection	<u>3/4"</u>		\$	
	Lead	Cock				
1	Curb	Valve	<u>3/4"</u>	in.		
		T. S. & V.				
1	Service box	Short 3 1/2 x 4 1/2				
	Old returned	Long 4 1/2 x 5 1/2				
		Buff. or Rdway				
<u>28</u>	<u>3/4"</u>	Copper		Pipe at		
		G. I.				
		C. I.				
	Nipples	in. at				
	Bushings	to in. at				
	Red'g } Coupl'gs	to in. at				
	Inc'g }					
	Union	in. at				
	Meter	in. at				
	Lead Joints	at				
	Compound Joints	at				
	Maintenance Foreman					
	Hrs. Water Maint. Man-1	at				
	Hrs. Water Maint. Man-2	at				
	Hrs. Garage Foreman	at				
	Hrs. Labor	at				
	Hrs. Compressor	at				
	Compensation Ins. at \$	per C				
	Trucking					
	Pav't Patch					
	O'head					

To be made July 7-17
By G. S. Gardner

St. Morton
 Pl. 11-15
 Ave. No. 11-15

Name of Owner Herman Delsignore

Labor and Mat'l. Report July 7 1917

Garage

● Curb Box

6" Main
Elev. of Main at tap 5 1/2'

Gate at ●
● Gate at

● Curb Box

#11 Tax ID # 309.7-7-2

LSM-SC-3-10-61