

LABOR AND MATERIALS

Copper	Lead	Connection	3/4		\$
1	Curb	Cock Valve T. S. & V.	3/4	in.	\$
1	Service Box	} Short 3 1/2 x 4 1/2 Long 4 1/2 x 5 1/2 Buffer Rdway			\$
	Old returned				\$
10	Ft.		3/4	in.	} Copper Galv Iron Cast Iron
	Nipples		in.	at	\$
	Bushings		to	in.	at \$
	Red'g Inc'g	Couplings		to	in. at \$
	Union		in.	at	\$
	Meter		in.	at	\$
	Lead Joints				\$
	Leadite Joints				\$
	Hrs. Foreman				at \$
	Hrs. Chauffeur				at \$
	Hrs. Tapper				at \$
	Hrs. Labor				at \$
	Hrs. Labor				at \$
	Hrs. Compressor				at \$
	Compensation Ins.				\$
	Trucking				\$
	Builders Use of Water				\$
					\$
					\$
					\$
					\$
					\$

St. 32W
 Pl. 36
 Ave. No.

Water Damage

Name of Owner
Geo M Douglas

Labor and Mat'l. Report *Aug 28* 19 *28*

● Curb Box

Elev. of Main at tap 5'

4 Main

Gate at ● ● Gate at

● Curb Box

Tax ID# 302.20-14-9