

Labor and Materials

Copper	}	Connection.....	\$	
Lead				
Curb	}	Cock	in	\$
		Valve		
		T. S. & V.		
Service Box	}	Short 3½ x 4½	\$	
Old returned		Long 4½ x 5½		
		Buff. or Rdway		
Ft. in.	}	Copper	Pipe at	\$
		Galv Iron		
		Cast Iron		
Nipples		in. at	\$	
Bushings		to	in. at	\$
Red'g	}	Conplings.....to	in. at	\$
Inc'g				
Union		in. at	\$	
Meter		in. at	\$	
Lead Joints at			\$	
Leadite Joints at			\$	
Hrs. Foreman at			\$	
Hrs. Chauffeur at			\$	
Hrs. Tapper at			\$	
Hrs. Labor at			\$	
Hrs. Labor at			\$	
Hrs. Compressor at			\$	
Compensation Ins.			\$	
Trucking			\$	
Builders Use of Water			\$	
			\$	
			\$	
			\$	
			\$	
			\$	
			\$	
			\$	

St. 33W
 Pl. 37
 Ave. No. 37

Name of Owner _____

Labor and Mat'l. Report Oct 28 1920

33W

● Curb Box

Main
Elev. of Main at tap.....

Gate at ●
● Gate at

● Curb Box

Tax 10# 302.20-3-24