LABOR AND MATERIALS

| | 3).' | | |
|-------------------|--|--|--|
| | Corb Cock 3/4 Or Iseal. | | |
| * | (Cock 1 3/1 Oriseal. | | |
| * | Curb Cock Valve In | | |
| * | Service Box Old returned Short 3½x4½ Short 3½x5½ | | |
| | Service Box Old returned Short 3½x4½ Long 4½x5½ Buffor Rdway S | | |
| | | | |
| 1160 | Gopper Galviron Pipe at\$ | | |
| | Nipplesin. at\$ | | |
| | Bushingstoin. at\$. | | |
| | Red'g la lines to in at\$ | | |
| | Red'g Couplingstoin. at | | |
| | Union | | |
| | Meterin, atss | | |
| | Lead Joints at\$ | | |
| | Leadite Joints at | | |
| | | | |
| Hrs. Chauffeur at | | | |
| Hrs. Tapper at | | | |
| | Hrs. Labor at \$ | | |
| l | Hrs. Labor at\$ | | |
| ١ | Hrs. Compressor at | | |
| İ | Compensation Ins. | | |
| ١ | Trucking | | |
| ١ | Builders Use of Water Super Su | | |
| | Tap by | | |
| | 10-9-69, \$ | | |
| | ************************************** | | |
| | | | |
| | \$ | | |
| | The state of the s | | |

| Notre Dani | St. 76W Pl. Ave. No. 78 | |
|------------------------|-------------------------------|--|
| Name of Owner Clifford | | |
| | Oct 9 | |
| Labor and Mat'l. Re | eport AUS 2 5 1939 19 69 | |
| | 76W | |
| | | |
| | | |
| 23' 0" | 26' 10" | |
| | | |
| | Curb Box | |
| 1.11 | 77.1 | |
| 6 Main | Elev. of 4 Main at tap | |
| Gate at | Gate at | |
| | | |
| | | |
| - | Curb Box | |
| | 2021/2 | |
| tax 10# | 302.19-28-16 | |
| | | |
| * | 900 V | |
| | | |