

LABOR AND MATERIALS

Copper	} Connection		\$	
Lead				
Curb	} Cock	in.	\$	
				} Valve
1 Service box	} Short 3 1/2 x 4 1/2			
Old returned		} Long 4 1/2 x 5 1/2		
			} Buff or Rdway	
Ft.	} Copper	Pipe at		\$
in.			} G. I.	
Nipples	in. at		\$	
Bushings	to	in. at	\$	
Red'g	} Coupl'gs	to	in. at	\$
Inc'g				
Union	in. at		\$	
Meter	in. at		\$	
Lead Joints	at		\$	
Compound Joints	at		\$	
Maintenance Foreman			\$	
Hrs. Water Maint. Man-1	at		\$	
Hrs. Water Maint. Man-2	at		\$	
Hrs. Garage Foreman	at		\$	
Hrs. Labor	at		\$	
Hrs. Compressor	at		\$	
Compensation Ins. at \$	per C		\$	
Trucking			\$	
Pav't Patch			\$	
			\$	
			\$	
			\$	
O'head			\$	
			\$	

St.
~~Pl.~~
Ave. No.

Oak

Name of Owner
Cunningham

Garage. Measured in
Labor and Mat'l. Report Aug. 31 1959

Curb Box

6" Main Elev. of Main at tap

Gate at • Gate at •
Shut off at Curb.
Building razed.

Curb Box

This Tap, for
garage, in back
of Stone Wall
on Oak St.

LSM-5C-2-556